

Michael O. Leavitt Governor Dianne R. Nielson, Ph.D. Executive Director Don A. Ostler, P.E.

ootstate 🕶 Utah

DEPARTMENT OF ENVIRONMENTAL QUALITY DIVISION OF WATER QUALITY

288 North 1460 West P.O. Box 144870 Salt Lake City, Utah 84114-4870 (801) 538-6146 (801) 538-6016 Fax (801) 536-4414 T.D.D. www.deq.state.ut.us Web

June 6, 2000

Mr. Chris Hansen, Environmental Coordinator Canyon Fuel Company, LLC Skyline Mines HC35 Box 380 Helper, UT 84526

Dear Chris:

Subject:

Reconnaissance Inspection at Dugout Mine UTG040020

Copy Mike
FAX PFO
ACTIONS/039
Sneonig

Water Quality Board

William R. Williams Vice Chairman

Ray M. Child, C.P.A.

John R. Cushing, Mayor

Dianne R. Nielson, Ph.D.

Douglas E. Thompson, Mayor

Ronald C. Sims, Ph.D.

J. Ann Wechsler Don A. Ostler, P.E. Executive Secretary

K.C. Shaw, P.E.

Robert G. Adams

Nan Bunker

On May 11, 2000 I completed a Reconnaissance Inspection of the Dugout Mine. No permit violations were observed during the inspection. We are requesting that, when mine water discharge first occurs, samples of mine water be taken for acute and chronic toxicity as well as heavy metals and ammonia nitrogen.

If you have any questions please give me a call at (801) 538-6058.

Sincerely,

Michael D. Herkimer, Environmental Scientist

Michael Warkemer

Permits & Compliance Section

MDH:cc

Enclosure

cc:

Pam Grubaugh-Littig, DOGM (W/encl)

Claron Bjork, Southeastern Utah District Health Department (W/encl)

Donna Inman, US EPA Region VIII (W/encl) David Ariotti, District Engineer (W/encl)

P:\WQ\PERMITS\MHERKIME\WP\HANSEN.LTR FILE:

| • | Unite | ed States Environment Washington, D. | | | Form Approved OMB No. 2040-0003 Approval Expires 7-31-85 | |
|---|--|---|--|-------------------|--|--|
| | Sec | tion A: National I | Data System Coding | | | |
| Transaction Code NPDES Yr/Mo/Day Inspection Type Inspector Fac Type 1 N 2 5 3 UITIGI0I4I0020 11 12 0 0 0 5 1 1 17 18 R 19 S 20 2 Remarks | | | | | | |
| 21 | | | | | | |
| Reserved Facility Eval | ВІ | BI QAReser | | | | |
| 67 69 70 71 N 72 N 73 74 75 80 | | | | | | |
| Section B: Facility Data | | | | | | |
| Name and Location of Facility Inspected CANYON FUEL COMPANY - DUGOUT MIN | | Entry Time | | 5/1/ | | |
| · · · · · · · · · · · · · · · · · · · | | Exit Time/Date | | | Permit Expiration Date 4/30/03 | |
| Name(s) of On-Site Representative(s) CHRIS HANSEN CANYON FUEL COMPANY, LLC SKYLINE MINES, HC 35 BOX 380, HELPER | Title(s) ENVIRONMENTAL COORDINATOR | | | | ne No(s) 5) 448-2669 | |
| Name, Address of Responsible Official | Title | | | | | |
| | Phone No. | Phone No. | | | ntacted | |
| | | | uated During Inspec = Unsatisfactory, N = | | | |
| Permit | Flow Measurement | | Pretreatment | | 0 | perations & Maintenance |
| Records/Reports | Laboratory | | Compliance Schedules | | sı | udge Disposal |
| Facility Site Review | Effluent/Receiving Water Self-Monitorin | | | ng Program | 0 | ther: |
| THE MINE SITE LOOKED GREAT. NO VIO LIKE EVENT FROM OCCURRING THROUG | | REQUIREMENT | S WERE NOTED. P | RECAUTIONS WERE 1 | AKEN TO | PREVENT ANOTHER FLOOD |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| Name(s) and Signature(s) of Inspector(s) MIKE HERKINER DIVISION OF WATER QUALITY | | | | | Date | 6/6/00 |
| Signature of Reviewer GAYLE J, SMITH Jule John | Agency/Office DIVISION OF WATER QUALITY | | | | Date | 6/6/00 |
| Regulatory Office Use Only | | | | | | |
| Action Taken | | | | Date | Cor | npliance Status Noncompliance Compliance |